



# Sample Program Approval Listing Composite Blade Certifications

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.

| Company/Location                                                              | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|-------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| <b>Hartzell MRO Network</b>                                                   |                                     |                                                       |                                                   |
| <b><i>Hartzell Service Center<br/>Piqua Ohio</i></b>                          | <b><i>#6/30/26</i></b>              | <b><i>1,2,3,4,5,6,7,8,9,10</i></b>                    | <b><i>5/31/27</i></b>                             |
| <b><i>American Propeller Service<br/>Redding California</i></b>               | <b><i>10/31/26</i></b>              | <b><i>1,2,5,6,7,8,10</i></b>                          | <b><i>6/30/33</i></b>                             |
| <b><i>Tiffin Aire<br/>Tiffin Ohio</i></b>                                     | <b><i>#6/30/26</i></b>              | <b><i>1,2,5,6,7,8,10</i></b>                          | <b><i>10/31/26</i></b>                            |
| <b><i>Texas Aircraft Propeller<br/>Pearland Texas</i></b>                     | <b><i>2/28/27</i></b>               | <b><i>2,7</i></b>                                     | <b><i>1/31/35</i></b>                             |
| <b><i>Canadian Propeller<br/>Winnipeg Canada</i></b>                          | <b><i>#1/31/28</i></b>              | <b><i>1,2,3,5,6,7,8,10</i></b>                        | <b><i>10/31/33</i></b>                            |
| <b><i>Brinkley Propeller Services Ltd<br/>Nr Shefford Bedfordshire UK</i></b> | <b><i>8/31/27</i></b>               | <b><i>2,7,8,10</i></b>                                | <b><i>5/31/30</i></b>                             |
| <b><i>Rocky Mountain Propeller<br/>Erie Colorado</i></b>                      | <b><i>2/28/27</i></b>               | <b><i>None Approved</i></b>                           | <b><i>N/A</i></b>                                 |

# Sample Program Approval Listing Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.

| Company/Location | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
|------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|

## Hartzell Recommended Service Facilities

|                                                                    |                 |                         |                 |
|--------------------------------------------------------------------|-----------------|-------------------------|-----------------|
| <i>Helices Clerici Propellers<br/>Buenos Aires Argentina</i>       | <i>3/31/29</i>  | <i>2,7</i>              | <i>9/30/32</i>  |
| <i>East Coast Propellers Pty. Ltd.<br/>Sydney Australia</i>        | <i>#4/30/27</i> | <i>1,2,3,7,8,10</i>     | <i>4/30/35</i>  |
| <i>West Coast Propellers Pty. Ltd.<br/>Perth Western Australia</i> | <i>10/31/27</i> | <i>3,7,8</i>            | <i>5/31/28</i>  |
| <i>Diamond Aviação Ltda<br/>Goias Brazil</i>                       | <i>1/31/28</i>  | <i>1,2,7,8</i>          | <i>7/31/26</i>  |
| <i>Diamond Aviacao<br/>Sao Paulo Brazil</i>                        | <i>1/31/28</i>  | <i>7,10</i>             | <i>8/31/32</i>  |
| <i>Canadian Propeller<br/>Winnipeg Canada</i>                      | <i>#1/31/28</i> | <i>1,2,3,5,6,7,8,10</i> | <i>10/31/33</i> |
| <i>Hope Aero Propeller and Components<br/>Ontario Canada</i>       | <i>3/31/29</i>  | <i>2,5,6,7,10</i>       | <i>9/30/29</i>  |

# Sample Program Approval Listing Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                                                   | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|--------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| <b><i>Technic Aviation<br/>Manosque France</i></b>                 | <b><i>2/28/27</i></b>               | <b><i>3,5,6,7,8</i></b>                               | <b><i>2/28/27</i></b>                             |
| <b><i>C &amp; A Aviation Ltd<br/>Malaysia</i></b>                  | <b><i>Not Approved</i></b>          | <b><i>2,5,6,7</i></b>                                 | <b><i>1/31/32</i></b>                             |
| <b><i>Airbus New Zealand<br/>Blenheim</i></b>                      | <b><i>Not Approved</i></b>          | <b><i>2,5</i></b>                                     | <b><i>Not Approved</i></b>                        |
| <b><i>Norronafly P &amp; P AS<br/>Oslo Norway</i></b>              | <b><i>4/30/27</i></b>               | <b><i>5,6,7,8</i></b>                                 | <b><i>8/31/34</i></b>                             |
| <b><i>Proptech Portsmouth LTD<br/>Portsmouth Hampshire UK</i></b>  | <b><i>#9/30/28</i></b>              | <b><i>2,3,4,5,6</i></b>                               | <b><i>9/30/35</i></b>                             |
| <b><i>Aviation Propellers Inc.<br/>Opa Locka Florida</i></b>       | <b><i>5/31/28</i></b>               | <b><i>5,6</i></b>                                     | <b><i>6/30/26</i></b>                             |
| <b><i>Jordan Propeller Service, Inc.<br/>San Antonio Texas</i></b> | <b><i>12/31/26</i></b>              | <b><i>2,6,7</i></b>                                   | <b><i>11/30/30</i></b>                            |
| <b><i>InterContinental Jet<br/>Tulsa Oklahoma</i></b>              | <b><i>10/31/27</i></b>              | <b><i>1,2,5,6,7,8,10</i></b>                          | <b><i>1/31/31</i></b>                             |

# Sample Program Approval Listing

## Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                                                                              | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|-----------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| <b><i>Maxwell Aircraft Service</i></b><br><b><i>Minneapolis Minnesota</i></b>                 | <b><i>6/30/26</i></b>               | <b><i>1,2,5,6,7,8,10</i></b>                          | <b><i>6/30/33</i></b>                             |
| <b><i>Northwest Propeller Service, Inc.</i></b><br><b><i>Puyallup Washington</i></b>          | <b><i>10/31/26</i></b>              | <b><i>2,7,8</i></b>                                   | <b><i>11/30/35</i></b>                            |
| <b><i>Ottosen Propeller</i></b><br><b><i>Phoenix Arizona</i></b>                              | <b><i>#Not Approved</i></b>         | <b><i>None Approved</i></b>                           | <b><i>N/A</i></b>                                 |
| <b><i>Piedmont Propulsion Systems, LLC.</i></b><br><b><i>Winston-Salem North Carolina</i></b> | <b><i>5/31/28</i></b>               | <b><i>2,5,7</i></b>                                   | <b><i>5/31/32</i></b>                             |
| <b><i>Argentina</i></b>                                                                       |                                     |                                                       |                                                   |
| <b><i>Argenprop SRL</i></b>                                                                   | <b><i>12/31/26</i></b>              | <b><i>None Approved</i></b>                           | <b><i>N/A</i></b>                                 |
| <b><i>Australia</i></b>                                                                       |                                     |                                                       |                                                   |
| <b><i>Australian Aero Propeller Maintenance</i></b><br><b><i>Dingley Victoria</i></b>         | <b><i>Not Approved</i></b>          | <b><i>3</i></b>                                       | <b><i>**2/28/28</i></b>                           |
| <b><i>Airflite Pty. Ltd.</i></b><br><b><i>Perth Western Australia</i></b>                     | <b><i>12/31/26</i></b>              | <b><i>3,6,7</i></b>                                   | <b><i>11/30/31</i></b>                            |

# Sample Program Approval Listing

## Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.**

| Company/Location                                                  | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|-------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| Prop Care Australia Pty Ltd.<br>Brisbane Queensland               | Not Approved                        | None Approved                                         | N/A                                               |
| Southern Propeller Service Pty. Ltd.<br>Salisbury South Aistralia | 4/30/27                             | 2,7,10                                                | 9/30/34                                           |
| <b>Brazil</b>                                                     |                                     |                                                       |                                                   |
| Global Parts LTDA<br>Goiania                                      | 11/30/29                            | 2,7                                                   | 12/31/35                                          |
| Runway Aviation Brazil<br>Goiania                                 | 11/30/29                            | 2,7                                                   | 12/31/35                                          |
| VMF Aeronautica Ltda<br>Votorantim                                | 11/30/29                            | 2,7                                                   | 8/31/35                                           |
| <b>Canada</b>                                                     |                                     |                                                       |                                                   |
| AMK Aviation Inc.<br>Murrillo Ontario                             | 5/31/28                             | 5                                                     | 3/31/28                                           |
| Propworks Propeller<br>Edmonton Alberta                           | 2/28/27                             | 5,7                                                   | 9/30/29                                           |

**Composite Blade Overhaul and Erosion Shield Replacement Approval Listing**  
**\* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319**

# Sample Program Approval Listing Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                                                  | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|-------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| Western Propeller Co. Ltd. - Pacific<br>Richmond British Columbia | 10/31/26                            | 2,5,6,,7                                              | 9/30/35                                           |
| <b>China</b>                                                      |                                     |                                                       |                                                   |
| Shenyang Avias<br>Shenyang                                        | 9/30/28                             | None Approved                                         | N/A                                               |
| <b>Columbia</b>                                                   |                                     |                                                       |                                                   |
| Aerohelices De Columbia<br>Bogota                                 | 2/28/29                             | None Approved                                         | N/A                                               |
| General Propeller Services SAS<br>Bogota                          | 8/31/28                             | 5                                                     | 6/30/32                                           |
| Sahar Group<br>Bogota                                             | 2/28/29                             | None Approved                                         | N/A                                               |
| <b>Denmark</b>                                                    |                                     |                                                       |                                                   |
| ScanAviation<br>Copenhagen                                        | 12/31/26                            | 2,5,7,8                                               | 1/31/34                                           |

# Sample Program Approval Listing Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                        | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|-----------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| <b><i>Germany</i></b>                   |                                     |                                                       |                                                   |
| MT Propeller GmbH<br>Atting             | #1/31/28                            | 1,2,4,5,6,7,8,10                                      | 9/30/31                                           |
| <b><i>Mexico</i></b>                    |                                     |                                                       |                                                   |
| ASI Propeller                           | Not Approved                        | None Approved                                         | N/A                                               |
| <b><i>Portugal</i></b>                  |                                     |                                                       |                                                   |
| Aerohelice LDA Alverca                  | 5/31/26                             | 2,5,7                                                 | 1/31/33                                           |
| <b><i>South Africa</i></b>              |                                     |                                                       |                                                   |
| Dynamic Propeller<br>Germiston          | 2/28/27                             | 2,5,6,7                                               | 8/31/31                                           |
| Joc-Air<br>Pretoria                     | 5/31/26                             | 1,2,5,6,7,10                                          | 7/31/33                                           |
| Propeller Centre<br>Les Marais Pretoria | 9/30/28                             | 2,5,6,7                                               | 3/31/36                                           |



# Sample Program Approval Listing Composite Blade Certifications

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                                         | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|----------------------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| <b><i>South Korea</i></b>                                |                                     |                                                       |                                                   |
| JCA Autonomous Co. Ltd.                                  | 8/31/29                             | 2,7                                                   | 8/31/32                                           |
| <b><i>Switzerland</i></b>                                |                                     |                                                       |                                                   |
| Pilatus Aircraft                                         | 12/31/26                            | 3,7                                                   | 5/31/29                                           |
| <b><i>USA</i></b>                                        |                                     |                                                       |                                                   |
| Aircraft Propeller Works<br>Auburndale Florida           | 9/30/28                             | 1,2,6,7,10                                            | 5/31/34                                           |
| Johnson Propeller<br>Shafter California                  | 1/31/28                             | None Approved                                         | N/A                                               |
| New England Propeller Service<br>East Haddam Connecticut | #6/30/26                            | 1,2,4,5,6,7,8,10                                      | 10/31/27                                          |
| Sensenich Propeller Service, Inc.<br>Gainesville Georgia | 5/31/28                             | 2,7,8,10                                              | 3/31/35                                           |
| Sensenich Propeller Service, Inc.<br>Lititz Pennsylvania | 8/31/28                             | 2,5,6,7,8,10                                          | 6/30/34                                           |

**Composite Blade Overhaul and Erosion Shield Replacement Approval Listing**  
**\* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319**



# Sample Program Approval Listing

## Composite Blade Certifications



Hartzell MRO's and Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing on our website.

Erosion Shield  
Replacement Blade  
Families are listed in the  
Hartzell Composite Blade  
Overhaul Manual 135F.

**\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to  
hold Erosion Shield Replacement Approval.**

| Company/Location                         | Overhaul/Major Repair<br>Expiration | Erosion Shield Replacement<br>Approved Blade Families | Erosion Shield Replacement<br>Approval Expiration |
|------------------------------------------|-------------------------------------|-------------------------------------------------------|---------------------------------------------------|
| Sullivan Propeller<br>Hayward California | 11/30/28                            | None Approved                                         | N/A                                               |
| Yingling Aircraft Inc.<br>Wichita Kansas | 10/31/26                            | 5,6,7                                                 | 3/31/35                                           |
| <b>Venezuela</b>                         |                                     |                                                       |                                                   |
| Aeroservicios Propeller<br>Aragua        | 8/31/28                             | None Approved                                         | N/A                                               |