

HARTZELL PROPELLER INC.
NON-AVIATION (MARITIME) SERVICE BULLETIN INDEX
February 11, 2026

HM-SB-001	Original	02/13/14	Restamping the hub and blade assemblies on affected Hovercraft propellers with maritime model numbers. Replating affected components with cadmium to meet current production specifications.
HM-SB-002	Original	01/05/23	Requires replacement of the pitch change knob brackets on affected propellers.
HM-ASB-003	Original	* 02/11/26	Requires pre-operation inspection of the beta rod nuts on affected propellers and removal of unauthorized safety wire if installed.

* Asterisk at end of service document number indicates documents released at the revision date of this listing or indicates a status change of documents, e.g., obsolete.